



## **COLLIN COUNTY OSSF INSPECTION LIST**

### **INSPECTION 1 SEPTIC INSTALLATION:**

1. INSTALLATION OF SYSTEM AS PER THE REGISTERED SANITARIAN'S (RS) OR PROFESSIONAL ENGINEER'S (PE) DESIGN. REDESIGN BY RS OR PE IS REQUIRED IF INSTALLED DIFFERENTLY.
2. TANKS MUST HAVE WATER ABOVE SEAMS ON TWO PIECE TANKS OR AT LEAST ½ FULL ON 1 PIECE TANKS.
3. SEPTIC TANKS AND LINES CANNOT BE COVERED, OR THE INSPECTION WILL FAIL.

**\*\*\*PERMIT & ADDRESS POSTED\*\*\***

### **INSPECTION 2 SEPTIC FINAL:**

1. INSPECTION OF SPRINKLER SPRAY AREA (ONLY FOR SPRAY IRRIGATION AEROBIC SYSTEMS)
2. THE USE OF A GENERATOR OR LINE FROM T-POLE PERMITTED BUT MUST BE CONNECTED TO METER BASE OR MAIN CIRCUIT PANEL. DO NOT HOOK DIRECTLY TO SUB PANEL.

**\*\*\*PERMIT & ADDRESS POSTED\*\*\***

**BOTH INSPECTIONS CAN BE DONE AT THE SAME TIME.**

***WE WILL RE-INSPECT ONE TIME AT NO CHARGE.  
A \$75 FEE WILL BE CHARGED FOR ADDITIONAL INSPECTIONS.  
THIS FEE MUST BE PAID BEFORE YOU CAN SCHEDULE FURTHER  
INSPECTIONS.***